



Due to a number of recent TPMS failures, please ensure all vehicles with these installed, regardless of manufacture, are inspected carefully and replaced as necessary. The pictures below show corrosion that has resulted in a failure.

One way to limit the speed of corrosion is to remove any metallic valve caps and replace with plastic. This will reduce the chance of the stem fracturing when a driver is adding/filling tires away from a Transervice facility. Please verify with your local dealer if any warranty remains on any units experiencing a problem or failure.

